3Rd QTR.

## COTTENWOOD HILLS GAS COLLECTION SYSTEM WORKSHEET FOR NSPS MONITORING REQUIREMENTS FOR QUARTERLY SURFACE MONITORING POTENTIAL METHANE CONCENTRATIONS AT LANDFILL SURFACE

INSTRUMENT: FOXBORO, TVA-1000B FLAME IONIZATION DETECTOR FOR TOXIC GAS VAPOR ANALYZING

MODEL: AB2BFAZ

S# 30987664

I.D.# 1505

CALIBRATION GAS: 1000 PPM METHANE GAS CONCENTRATION

400 PPM ON EXCEEDANCE TESTING

**INSTRUMENT TRAINING: OPERATION/ CALIBRATION** 

PROVIDED BY FOXBORO VIDEO AND O'BRIEN ENVIRONMENTAL CORP.

## **MONITORING METHOD:**

**CALIBRATE** 

ESTABLISH BACKGROUND CH4 CONCENTRATION LEVEL UPWIND AND DOWNWIND OUTSIDE OF LANDFILL BOUNDARY, 30m FROM PERIMETER WELLS

EXCEEDANCE LEVEL IS 500 PPM, RECORDED AND MARKED LOCATIONS

COVER PERIMETER OF COLLECTION AREA AND FOLLOW SERPENTINE PATTERN AT 30m INTERVALS, BISECTING DISTANCE BETWEEN WELLS TO VERIFY ROI EFFICIENCY

PROBE DISTANCE TO SURFACE: 5-10 cm OR TOP OF VEGETATION METER READINGS TO HIGHEST PPM LOCATION AND HOLD FOR TWICE THE INSTRUMENTS RESPONSE TIME.

SEE ATTACHMENT MAP FOR SITE WALK PATTERN.

## COTTENWOOD HILLS GAS COLLECTION SYSTEM WORKSHEET FOR NSPS MONITORING REQUIREMENTS FOR QUARTERLY SURFACE MONITORING POTENTIAL METHANE CONCENTRATIONS AT LANDFILL SURFACE

| DATE: 9-10-12                               | TEMP. 79                                   |
|---|--|
| TIME: /30/                                  | WIND DIRECTION S. E.                       |
| TECHNICIAN D'Egni gu                        | wind direction S. E.  SITE CONDITIONS WET. |
| INSTRUMENT CALIBRATED YES                   |  |
| BACKGROUND LIMIT PP                         | M W. 4.1 E 1-1 5,21                        |
| RECORDED EXCEEDANCES: ITEM 1. Nothing found | OVER 40-PPM PPM                            |
| 2.  | PPM  |
| 3.  | PPM  |
| 4.  | PPM  |
| MAINTENANCE OR ADJUSTMENTS TO               | BE MADE.                                   |
| ITEM 1.                                     | PPM  |
| 2.  | PPM  |
| 3.  | PPM  |
| 4.  | PPM  |
| 2ND EXCEEDANCE CHECK (WITHIN 10             | CALENDAR DAYS) REMONITORING RESULTS.       |
| ITEM 1.                                     | PPM  |
| 2.  | PPM  |
| 3.  | PPM  |
| 4.  | PPM  |

|          | 3RD EXCEEDANCE CHECK (WITHIN 20 CALENDAR DAYS) REMONITORING RESULTS.                              |                                    |
|----------|---|------------------------------------|
|          | ITEM 1.   | PPM                                |
|          | 2.  | РРМ                                |
|          | 3.  | РРМ                                |
|          | 4.  | PPM                                |
|          |   |                                    |
|          | ADDITIONAL CONTROL MEASURES TO BE TAKEN   |                                    |
|          | ITEM 1.   | PPM                                |
|          | 2.  | PPM                                |
|          | 3.  | PPM                                |
|          | 4.  | PPM                                |
| 16-25-12 | REMONITORING RESULTS (FOR EXCEEDANCES < 500 PPI<br>REMONITORING EVENTS) WITHIN 1 MONTH OF INITIAL | M DURING 2ND,OR 3RD<br>EXCEEDANCE. |
| 10       | ITEM 1. Nothing   | PPM                                |
|          | 2.  | PPM                                |
|          | 3.  | РРМ                                |
|          | 4.  | PPM                                |
|          | COMMENTS:   |                                    |
|          | REVIEWED BY:  | DATE:                              |

